








Diameter  
in mm

- $\varnothing$
- 0,12
- 0,16
- 0,20
- 0,22
- 0,25
- 0,30
- 0,35



$\Delta$  = Coated  
 $\nabla$  = Guidance Tube  
 # = Needles per Package



**SILK**  $\delta$  # 100

**SILK**<sup>PLUS</sup>  $\delta$   $\nabla$  # 100

$\delta$   $\nabla$  # 1000

Diameter  
in mm



0,12

0,16


0,20

0,22

0,25

0,30

0,35




**TCM** # 100

$\delta$  # 100

$\delta$   $\nabla$  # 1000

$\nabla$  # 1000

$\delta$  = Coated  
 $\nabla$  = Guidance Tube  
 # = Needles per Package



**STEEL** # 100

$\delta$  # 100

# 1000

$\delta$   $\nabla$  # 100

